

INSTALLATION INSTRUCTIONS for R-30 Bullet

Tools Needed: Adjustable Torque Screwdriver (set to 15 in/lb)



1. Install gasket onto lens by inserting glass lens into gasket. Gasket is non-directional.



 [Installation Video](#)

INSTALLATION INSTRUCTIONS (cont.)

2. Slip shield over bullet and position shield in required orientation.



3. Insert Lens+Gasket into shield/bullet assembly.



 **Installation Video**

INSTALLATION INSTRUCTIONS (cont.)

4. Using adjustable torque screwdriver, torque locking bolt to 15in/lb.



 [Installation Video](#)